

## WV-XAE207W Release Note

VER Release Date	Priority Rank Level					Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
1.00 Mar., '21						First production		
1.10 June, '21	U				x	-	-	Supports new cameras: WV-S1136, WV-S2136, WV-S2136L, and WV-S2236L *Those cameras need to be upgraded to version 1.11 or later to use WV-XAE203W.
1.20 Dec., '21	B				x	-	-	Updated external interface specifications. For details, refer to "AI Occupancy Detection Application (WV-XAE207W) External Interface Specification【C0319】" at the following link. <a href="https://i-pro.com/global/en/surveillance/training-support/support/technical-information">https://i-pro.com/global/en/surveillance/training-support/support/technical-information</a>
			x			The [Connection Settings] tab freezes after clicking the "Set" button. (Occurrence frequency: High)	When the last character of the path entered in "Transmission path name" is yen symbol (¥) or backslash (\).	Fixed.
			x			An incorrect path is displayed in "Transmission path name" on the [Connection Settings] tab after clicking the "Set" button. (Occurrence frequency: High)	When the path entered in "Transmission path name" includes one of the followings: - yen symbol (¥) - backslash (\) - consecutive greater-than symbols (>)	Fixed.
1.30 Mar., '22					x	-	-	Supports new cameras: WV-S8543, WV-S8543G, WV-S8544, WV-S8544G, WV-S8543L, WV-S8543LG, WV-S8544L, WV-S8544LG, WV-S8563L, WV-S8563LG, WV-S8564L, WV-S8564LG, WV-S8573L, WV-S8573LG, WV-S8574L, WV-S8574LG