

WV-XAE203W Release Note

VER Release Date	Priority Rank Level				Contents			
	A	B	C	U	Issue (Phenomenon)	Occurrence condition	Correspondence	
1.00 Dec., '20					First production			
1.10 June, '21	B				x	-	Supports new cameras: WV-S1136, WV-S2136, WV-S2136L, and WV-S2236L *Those cameras need to be upgraded to version 1.11 or later to use WV-XAE203W.	
					x		Supports detection frame display on i-PRO Configuration Tool version 2.0*. *To be released in the end of June.	
				x		The image may not be displayed at the frame rate selected in [Frame rate*]. (Occurrence frequency: High)	In case of simultaneous operation of AI Privacy Guard (WV-XAE201) and WV-XAE203W	Added the function to limit the frame rate of the target stream for WV-XAE201W to fix this phenomenon: - Up to 10 fps for WV-X series camera - Up to 5 fps for WV-S series camera
				x		The demo screen does not appear. (Occurrence frequency: High)	When the number assigned to [HTTP port] is not "80" in the camera setting	Fixed.
			x			WV-XAE203W restarts. (Occurrence frequency: High)	When the demo screen is opened and closed repeatedly.	Fixed.
					x			Improved the visibility of the demo screen as below: - Changed the color of "Unknown status" frame from green to blue - Removed the status display for blue frames ("Unknown" and "Mask")
1.10 June, '21	B				x	Alarm occurrence indication button on the live image and the detection frames on the demo screen may not be displayed. (Occurrence frequency: Rare)		Fixed.
					x			
1.20 Mar., '21	U				x	-	Supports new cameras: WV-S8543, WV-S8543G, WV-S8544, WV-S8544G, WV-S8543L, WV-S8543LG, WV-S8544L, WV-S8544LG, WV-S8563L, WV-S8563LG, WV-S8564L, WV-S8564LG, WV-S8573L, WV-S8573LG, WV-S8574L, WV-S8574LG	